

Panasonic
Communication Systems Division
Technical Advisory

Updated: Nov. 16,
00

Subject: KX-TD1232 Systems Interconnection

Document Number: KXTD1232008

Before you start, Insure that both cabinets have compatible software versions installed.*

Hardware Requirement

- Two KX-TD1232 systems with compatible software.
- One KX-TD192 Interconnection Kit.

System Startup for New Installation

Before you start, Insure that both cabinets have compatible software versions installed.*

1. With to power to both systems off install the KX-TD192 interconnection kit.
2. Set the Master/Slave switch on the Master to the Master position and the Slave to Slave position.
3. Place both system switches to the **CLEAR** position.
4. Power on **BOTH** systems.
5. When **BOTH** Power lights flash move both system switches to the **NORMAL** position.
6. **You must now wait at least FOUR minutes with NO ACTIVITY AT ALL on the system (This means NO C.O. calls and NO intercom calls).**
7. Now that you have waited Four minutes test cabinet to cabinet communications.
8. Program the system as required.

Adding a Second Cabinet to an Existing System

Before you start, Insure that both cabinets have compatible software versions installed.*

1. With the power off set the Master/Slave switch on the Slave to Slave position.
2. Place the System switch on the **SLAVE ONLY** to the **CLEAR** position.
3. Power on the **SLAVE** system **ONLY**.
4. When the Power lights flash move the system switches to the **NORMAL** position.
5. Power off **BOTH** systems and install the KX-TD192 interconnection kit.
6. Power on **BOTH** systems simultaneously.
7. **You must now wait at least FOUR minutes with NO ACTIVITY AT ALL on the system (This means NO C.O. calls and NO intercom calls).**
8. Now that you have waited Four minutes test cabinet to cabinet communications.
9. Program the system as required.

*

If you are unsure of your systems software compatibility, Have the serial number and version of both cabinets and call Panasonic Tech Support at 1-201-392-4843 or fax the information to 1-201-348-4641.